001 00 Page 1/(2 blank)

ALPHABETICAL INDEX

INSTALLATION AND REPAIR PRACTICES

AIRCRAFT ELECTRIC AND ELECTRONIC WIRING

	WP/
<u>Title</u>	Number
Aircraft Wiring and System Inspection	004 01
Bonding and Grounding	017 00
Bonding Classes	
Bus Bar and Terminal Board	019 00
Connector Accessories	024 00
Connector Cleaning and Preservation	026 00
Contacts, Terminals, Splices and Caps	013 00
Definitions and Symbols	003 00
Emergency Repairs (U.S. AIR FORCE AND ARMY ONLY)	015 01
Environmental Sealed Harness Repair	
Flat (Ribbon) Cable and Assemblies	
Harness Installation	
Heating Tools	012 00
Introduction	
List of Technical Publication Deficiency Reports (TPDR) Incorporated	
Lockwiring and Shearwiring	
Low Frequency, Multiconductor Round Cable Description and Replacements	005 00
Military Standard Circular Connectors	
Military Standard Rectangular Connectors	
MIL–PRF–39012 Radio Frequency Connectors	
Numerical Index of Effective Work Packages/Pages	
Open and Overbraided Harness Repair	
Potting and Sealing Connectors, Electrical Cable Assemblies, and Electrical Components	
Protective Devices	
Radio Frequency (RF) Cable Characteristics and Replacements	
Radio Frequency Connectors	
Ribbonized, Organized, Integrated (ROI) Harness Repair	
Shield Terminations ————————————————————————————————————	015 00
Soldering	016 00
Terminal Junction System	
Wire and Cable Splicing and Repair	
Wire and Cable Stripping	
Wire Characteristics and Substitutions	
Wire Cable, and Harness Marking	

NAVAIR 01-1A-505-1 TO 1-1A-14 TM 1-1500-323-24-1

015 00 Page 12

UNACCEPTABLE TERMINATION (INSUFFICIENT HEAT)

DULL RED COLOR (THERMAL INDICATOR) IS CLEARLY VISIBLE.

ORIGINAL SHAPE OF SOLDER PREFORM IS CLEARLY VISIBLE.

MELTABLE SEALING INSERTS HAVE NOT FLOWED.

CONTOUR OF BRAID AND/OR LEAD IS BLOCKED BY SOLDER.




SLIGHT TRACES OF DULL RED COLOR SHALL BE PRESENT.

SOLDER HAS LOST ALL ORIGINAL SHAPE.

SEALANT INSERTS HAVE MELTED AND FLOWED ALONG WIRES.

SHIELD AND LEAD CONTOURS ARE VISIBLE.

A DEFINITE FILLET IS VISIBLE BETWEEN LEAD AND SHIELD.



DULL RED COLOR HAS DISAPPEARED.

NO TRACES OF DULL RED COLOR REMAIN IN THE SEALANT INSERT AREA. SLIGHT TRACES OF DULL RED COLOR IN SEALANT INSERT AREA ARE ACCEPTABLE.

A DEFINITE FILLET IS CLEARLY VISIBLE BETWEEN LEAD AND SHIELD.

JOINT AREA IS VISIBLE DESPITE BROWNING OF SLEEVE.

UNACCEPTABLE TERMINATION (OVERHEATED)

JOINT AREA IS NOT VISIBLE BECAUSE OF SEVERE DARKENING OF THE OUTER SLEEVE.

SOLDER FILLET IS NOT VISIBLE ALONG LEAD AND SHIELD INTERFACE.

WIRE INSULATION DAMAGED OUTSIDE OF SLEEVE.











015 00 Page 13

A. GROUND LEAD PREPARATION.


 IF GROUND WIRE IS NOT PRE-INSTALLED, SELECT WIRE FROM MIL-W-22759



B. SHIELD PREPARATION
1. STRIP 1/4 TO 5/16 INCH OF JACKET FROM CABLE.



CENTER STRIPPED FOR CABLES RATED ABOVE 257°F (125°C)




END STRIPPED FOR CABLES RATED ABOVE 257°F (125°C)

AFTER STRIPPING, BUILD UP DIAMETER OF SMALL CABLE BY FOLDING BRAID OVER JACKET.

Folding the braid back over the jacket avoids the risk of braid to wire shorts after installing the solder sleeve termination.

Shorts can happen months after the solder sleeve terminations have been applied & inspected if the braid is not folded back.



BRAID FOLDED BACK FOR SMALL CABLE RATED BETWEEN 221'F (105 C) AND 257'F (125°C)

Figure 16. Immersion Resistant and Standard Solder Sleeve Installation (Sheet 1 of 3)

015 00 Page 14

C. ASSEMBLY.

 Assemble Cable, Ground Lead, and Solder Sleeve Ensuring No Strands Protrude to Puncture Sleeve. Ground Lead Entry May Be From Front or Rear.

WARNING

Do not perform hot work without specific authorization of activity Aviation Gas Free Engineer (AVGFE) or Gas Free Engineer (GFE).

The HT-900B, HT-920B, HT-71002 and MCH-100-A heat guns are the only authorized heat guns to be used when working on aircraft that have not been defueled and purged. The aircraft must be defueled and purged before using any other heat guns listed in this manual.

Aircraft with open fuel cells or broken or open fuel lines shall be certified gas free in accordance with NAVAIR 01-1A-35. Only the HT-900B/HT-920B, HT-71002, MCH-100-A heating tools are authorized for use on any aircraft whenever AVGAS, JP-4 or the presence of fuel is imposing an immediate danger.

When using heat guns with electric motors, recertification may be required as work progresses, as directed by the Aviation Gas Free Engineering Technician (AVGFET).

The MCH-100-A heat gun has been electromagnetic interference (EMI) qualified for flight line or flight deck use. All other electric motor type heat guns are not authorized for flight line or flight deck use due to electromagnetic interference (EMI). The electric motor type heating tools are safe for use by Navy/Marine Corps personnel at the organizational maintenance level to repair aircraft wiring in a hangar or hangar deck environment, provided the aircraft meets the gas-free environment criteria (NAVAIR 01-1A-35), and there are no EMI restrictions


Use of nitrogen with the HT-900B/HT-920B heating tool in an enclosed area can be hazardous. Discharge of nitrogen into a poorly ventilated area can result in asphyxiation.

Do not perform wire repair while using explosive solvent/paint products on the aircraft.

Nozzle and output air of heating tools get very hot. Use extreme care while operating heating tool to avoid serious burns.

When using a heat tool, do not use electrical power from the aircraft being repaired. Use electrical power from a ground power unit.


Using Heat Gun, Apply Heat Directly to Solder Perform Until Solder Melts, Flows and Wets Shield Braid and Ground Lead.



This method has a risk of braid to wire shorts happening after installation & inspection.

END STRIPPED





Use this method for TEFZEL wiring to avoid risk of braid to wire shorts. Shorts can happen after solder sleeve application & inspection.




Figure 16. Immersion Resistant and Standard Solder Sleeve Installation (Sheet 2)